

# F200

Firmware Version	Features	Release Date
<b>FW v4100.24</b>	<ul style="list-style-type: none"><li>&gt; Added alternate HTTP port option</li><li>&gt; Corrected temperature over/under thresholds for negative degF values</li><li>&gt; Added sensor disconnect to Modbus secondary register 40006</li><li>&gt; Added new Modbus register for connected devices (40006) to the "View Registers" page</li></ul>	5/27/2021
<b>FW v4100.27</b>	<ul style="list-style-type: none"><li>&gt; Corrected the Modbus/tcp reset when the web GUI is opened</li><li>&gt; Corrected the trending gaps and reduced trend logs due to sd card bad sectors</li><li>&gt; Changed the trending max log entries to 43200</li><li>&gt; Changed the GUI trending "max log time" base to 43200 entries</li></ul>	12/16/2021