F200

Firmware Version	Features	Release Date
FW v4100.24	 Added alternate HTTP port option Corrected temperature over/under thresholds for negative degF values Added sensor disconnect to Modbus secondary register 40006 Added new Modbus register for connected devices (40006) to the "View Registers" page 	5/27/2021
FW v4100.27	 Corrected the Modbus/tcp reset when the web GUI is opened Corrected the trending gaps and reduced trend logs due to sd card bad sectors Changed the trending max log entries to 43200 Changed the GUI trending "max log time" base to 43200 entries 	12/16/2021
FW v4100.30	> Add 1-Wire sensor support > Add debugging information	11/8/2024