

Application/ Program Version	Features	Hardware Required	Beta Release
5.0.3	Beta Release-Phase2	ASSY-FPC-001-E	6/25/2010
5.0.4	Corrected http layer for .html (may cause firewall issues)	ASSY-FPC-001-E	7/7/2010
5.0.5	Debugged EIA-485 option card	ASSY-FPC-001-E	7/13/2010
5.0.6	Corrected http post for smtp password mask "****"	ASSY-FPC-001-E	8/5/2010
5.0.7	Added wordorder="little" to xml file	ASSY-FPC-001-E	8/11/2010
5.0.8	Changed falcon logo to raptor logo	ASSY-FPC-001-E	8/25/2010
5.0.9	Corrected port 2 & 3 1200 baud timing. Corrected max device response time display for 9.9 Improved ie8 tcp timeout for cfg download	ASSY-FPC-001-E	9/21/2010
5.1.0	Added bacnet mstp slave to eia-485 port 3. Added bacnet engineering units and reference web page. Added bacnet writes for description and eng units.	ASSY-FPC-001-E	11/2/2010
5.1.1	Corrected DST	ASSY-FPC-001-E	11/3/2010
5.1.2	Added Timeticks to valid snmp response	ASSY-FPC-001-E	11/8/2010
Bootloader Version	Features	Hardware Required	Beta Release
5.0.0	Initial Release	ASSY-FPC-001-E	5/10/2010
5.0.1	Reduced flash blank check time for command prompt TFTP uploads.	ASSY-FPC-001-E	6/8/2010
5.0.2	Added menu command "485test" - loopback test for 485 option card com2-com3	ASSY-FPC-001-E	7/30/2010
5.0.3	Added serial flash SST25VF032B	ASSY-FPC-001-E	8/20/2010
5.0.4	user prgm erase sped up - skips erasing blank sectors	ASSY-FPC-001-E	11/2/2010